



# Gulfstream Inboard Flight Spoilers

P/N 1159CSH40050-1/-2

- GIV Spoilers with delamination, corrosion on aluminum plate from under graphite plies. These units are NEVER beyond economical repair. DAS has extensive tooling, engineering, and experience completely rebuilding these for a fraction of the price of new or an exchange. DAS offers turn times so low we can often eliminate any exchange requirements. Complete rebond with new fitting plates and the fastest turn time.



## Aircraft Bonding, Engineering, Tooling and Structural Modification

1456 Edgefield Way  
Cedar Hill, TX 75104

[www.dasvcs.com](http://www.dasvcs.com)

Tel 972.723.3164  
Fax 972.992.3932

FAA XQDR264Y  
EASA 145.6160

*Integrity In The Process | Quality In The Repair*