

Challenger 300 Inlet Repair

In support of Challenger 300 series aircraft, presenting with corrosion on the attachment ring and delamination of the composite structure during inspection, we have created a program for the repair and overhaul of the inlet assembly.

DAS has invested heavily in the support of Challenger 300 aircraft with advanced tooling, materials, and engineering to support the operator. DAS has created a very cost effective solution for the repair of the Inlet Assembly with a dedicated focus on quick turn-time and high quality repairs.

- **FAST & ACCURATE QUOTING**
- **21-DAY TURN TIME**
- **FULL SET OF LOANER/EXCHANGE INLETS**



**Corrosion of the Attachment Ring
Mounting Holes**

**Delamination of the
Composite Structure**



Aircraft Bonding, Engineering, Tooling and Structural Modification

1456 Edgefield Way
Cedar Hill, TX 75104

www.dasvcs.com

Tel 972.723.3164
Fax 972.992.3932

FAA XQDR264Y
EASA 145.6160

Integrity In The Process | Quality In The Repair